

At the writing of this white paper, Vendura has repaired over 160 of our competitors' installed shower bases. For whatever reason that the repair is required, it is worth noting that our customers call us instead of the original manufacturer.


This particular repair was in Round Rock, TX. 42 Neo with catastrophic damage to the drain area.



The event causing the damage is unknown, but it was strong enough to bend the brass drain. You don't see that every day.



The damaged drain area extended outward in multiple directions.



David Rusher, our in-house chemist and repairman, utilized Vendura's easy-to-use repair kit to fill the damaged areas. Our repair kits provide a fully welded area, no seams, no knit lines, and no weak bonds. These kits are not 3rd party products. They consist of the proper resin, filler, and colorants that are consistent with the original material.

After proper curing, the areas are sanded, as shown below.





Nice work David!