

“You don’t need to tear out the entire shower, we can just fix the shower base.”

These were words of great joy for our customer in Fitchburg WI.

Vendura was hired to completely remove a competitor’s damaged shower base and replace it with a new unit. This normally requires several trades, long downtime for the room, lots of coordination, and high costs. When our repairman, David Rusher, visited the job site and saw the localized damage to the shower base, he suggested cutting out the shower base floor, fixing the damage and re-installing the floor. No need to involve other trades and no need to coordinate with multiple companies, it reduces cycle time and saves money. The customer’s exact comment was “you can do that?”, Vendura’s response, “of course we can!”

David cut out the shower floor, repaired the damaged area on-site, and re-installed the floor. It now drains correctly and looks fantastic!


Vendura has the material science knowledge and the hands-on experience to repair shower bases that are already installed. Save time, save money, and work with the experts.

Vendura is part of the [BreakthrU Family of Companies](#). We are a supplier of specialized solid surface/epoxy/urethane solutions. Unique shower pans, wall protection, accessories, behavioral health drains, and installation/repair services. Let us help you connect architecture to art!

Before



During



After

